



MERCEDES E BREAK: 1LRB631

Vinnumber:	WDD2122011B290735	Versionname:	2.1 E 220 BLUETEC 120KW AVANTGARDE
First Registrationdate:	10/11/2015	Fiscalpower:	
Expertise Mileage:	112303	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4703
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/17/92 MS LightMetal				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2682,58
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Crack, Le - Replace and paint

766,80



Door moulding Lower F L, Deformed / Strained, E - Replace

132,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

420,00



Wing R L, Scratch(es), It - Spot repair

115,56



Windscreen, Stone chip(s), E - Replace

560,64



Bumper F, Dent(s), It - Spot repair

115,56



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02

