



MERCEDES C COUPE: JH6630

| | | | |
|------------------------------------|--------------------------|--------------|----------------------|
| Vinnumber: | WDD2053041F695583 | Versionname: | C 220 d 125kW |
| First Registrationdate: | 18/01/2018 | Fiscalpower: | |
| Expertise Mileage: | 53223 | Power Kw: | 125 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1429 |
| Number of doors: | 3 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|---------------------------------------|
| Radio CD | Seats electric F L |
| GPS storage | Seats electric F R |
| Windows electric F | Central consol F |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | No Tow bar |
| Type of GPS | Headlighting LED |
| Type of Lining | GPS big screen color |
| Type of climate control | Lining semi-artificial leather |
| | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/50/17/94 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--|--------------|
| Total cost ex VAT | 63,00 |
| Wing R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Dent(s), PDR - Paintless dent repair | 63,00 |



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display