



SEAT ALHAMBRA: 1TMH455

Vinnumber:	VSSZZZ7NZJV516719	Versionname:	1.4 TSI 110kW DSG Style Advanced
First Registrationdate:	12/12/2017	Fiscalpower:	
Expertise Mileage:	39975	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1724
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/92 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	1462,48
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Dent(s) and scratch(es), Le - Replace and paint

735,00



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Door frame F L, Deformed / Strained, Repair/replace (lump sum)

37,00



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Rearlight L, Crack, E - Replace

114,00

