



RENAULT ESPACE: ZX8778

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF1RFC00256622433 | Versionname: | Energy dCi 160 EDC Initiale Paris |
| First Registrationdate: | 16/12/2016 | Fiscalpower: | |
| Expertise Mileage: | 77993 | Power Kw: | 118 |
| Bodytype: | | Body color: | Purple |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3116 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| TV/DVD screen R | | Seats R heated | |
| GPS storage | | Seats electric F L | |
| GPS storage | SD | Seats electric F R | |
| Windows electric F | | Sun Roof electric | |
| Windows electric R | | Panoramic roof | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Seats F heated | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting LED | Type of Tow bar | No Tow bar |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | NOT OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/55/19/105 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 3 mm | Re.R. | Continental: 3 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|---------------|
| Total cost ex VAT | 367,56 |
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |


Door seal R L, Deformed / Strained, E - Replace

60,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Rearview mirror R complete, Broken, E - Replace

192,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), Acceptable

0,00

No pictures to display