



RENAULT CLIO: 1LTA973

Vinnumber:	VF15R0J0A54168242	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	27/11/2015	Fiscalpower:	
Expertise Mileage:	78331	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4101
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 MS Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 987,94

Wheel cover F L, Scratch(es), E - Replace 24,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

24,00




Interior, Dirty, Cleaning

25,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Dent(s), LI - Repair and paint (complete)

232,06



Wheel cover R R, Deformed / Strained, E - Replace

24,00



Rear window, Scratch(es), E - Replace

320,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Maintenance, Maintenance, Execute

0,00

No pictures to display