


**NISSAN QASHQAI: 1JKK521**

Vinnumber:	<b>SJNFDAJ11U1145266</b>	Versionname:	<b>1.6 DCI CONNECT EDITION</b>
First Registrationdate:	<b>9/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>143170</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4714</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Panoramic roof	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/17/96 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	48,00
-------------------	-------



Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Centre console, Scratch(es), Acceptable	0,00
---	------

<i>No pictures to display</i>		
Trunk lid covering R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rear wiper blade, Deformed / Strained, Acceptable		0,00
		
Interior, Dirty, Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper moulding F L, Deformed / Strained, LI - Repair and paint (partial)		48,00
		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		