



PEUGEOT 308 SW: 1LJP278

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber: | VF3LCBHY8FS249548 | Versionname: | 1.6 BLUEHDI 73KW BUSINESS LINE |
| First Registrationdate: | 6/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 77489 | Power Kw: | 73 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4627 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
| | 195/65/15/81 T Steel | | | |
| Winter tyres: | Fr.L. | BF Goodrich: 4 mm | Fr.R. | BF Goodrich: 4 mm |
| | Re.L. | BF Goodrich: 4 mm | Re.R. | BF Goodrich: 4 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

No pictures to display