



**RENAULT TRAFIC: 1BDG607**

Vinnumber:	<b>VF1FLBHA6BY374308</b>	Versionname:	
First Registrationdate:	<b>5/05/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>200757</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>CONTROLEREN</b>	Parking lot:	<b>TRU15</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/65/16/107 T Steel</b>				
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	1533,97
Door F R, Scratch(es), LI - Repair and paint (complete)	238,76



Wheel cover F R, Scratch(es), E - Replace



Interior, Damaged, Acceptable 0,00



Seat cover F R, Burned, Smart repair 64,32



Door F L, Scratch(es), Acceptable 0,00



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Sliding door R, Dent(s), Acceptable 0,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 328,88



Ignition key, Missing, E - Replace

150,00

No pictures to display

Bumper trim R, Deformed / Strained, E - Replace

375,09



Wheel cover R R, Scratch(es), E - Replace

22,50



Bumper F, Broken, Smart repair

110,64

