



VOLKSWAGEN PASSAT VARIANT: 1LKH260

Vinnumber:	WVWZZZ3CZGE087135	Versionname:	1.6 TDI VARIANT HIGHLINE
First Registrationdate:	12/10/2015	Fiscalpower:	
Expertise Mileage:	81634	Power Kw:	88
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Body color:	GRIJS
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	-16 DAGEN	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3710
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Seats electric F L	
GPS storage	SD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/98 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	No	Compressor	No
Emergency spare wheel	No	Jack	No
Repair kit	No	Runflat	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Compressor, Missing, E - Replace	0,00
----------------------------------	------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

