



VOLVO V40: 1LUY010

Vinnumber:	VV1MV7431G2317097	Versionname:	2.0 D2-82 KINETIC
First Registrationdate:	11/12/2015	Fiscalpower:	
Expertise Mileage:	77741	Power Kw:	88
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	2125
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	627,00
-------------------	--------

Bumper R, Missing, E - Replace	415,20
--------------------------------	--------



Alloy rim F L, Scratch(es), I - Repair 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), I - Repair 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Repaired, Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

