



VOLVO V60: GL9571

Vinnumber:	YV1FW79C1G1298211	Versionname:	2.0 D3 KINETIC R-DESIGN
First Registrationdate:	24/09/2015	Fiscalpower:	
Expertise Mileage:	134775	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/40/18/95 W LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1224,99
Sill outer R, Scratch(es), It - Spot repair	115,56



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Backrest cover F L, Damaged, Smart repair

64,32



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display


Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Outer door handle R R, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror glass R, Broken, E - Replace

18,00

