



**VOLVO V60: 1HNU884**

Vinnumber:	<b>VV1FW8481F1232888</b>	Versionname:	<b>V60 BRE D2 Kinetic 115PK</b>
First Registrationdate:	<b>1/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>164218</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>0 KM</b>	Parking lot:	<b>3105</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1710,47</b>
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Bumper F, Broken, LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Foglight R, Broken, E - Replace

138,00



Bumper Trim F, Hole, E - Replace

35,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Bonnet, Dent(s), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Repaired, Acceptable

0,00



Maintenance, Maintenance, Execute

0,00

*No pictures to display*

Wing R L, Bad repair, P - Check

0,00



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Spoiler R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Repaired, Acceptable 0,00



Door F R, Bad repair, P - Check 0,00



Door R L, Repaired, Acceptable 0,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror basis L, Broken, E - Replace 274,24

