



VOLVO XC60: 1JKD940

Vinnumber:	YV1DZ31A1F2692517	Versionname:	D3 Kinetic 136PK
First Registrationdate:	8/01/2015	Fiscalpower:	
Expertise Mileage:	155305	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1226
Maintenance:	OVER 9306 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/18/107 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1257,05
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R L, Scratch(es), Acceptable 0,00



Door panel F L, Tear, E - Replace 132,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Door panel R L, Tear, E - Replace 132,00




Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Door F L, Scratch(es), Acceptable 0,00



Floor covering F L, Tear, E - Replace 264,00



Door R L, Scratch(es), Acceptable 0,00



Backrest cover F L, Worn, P - Check

0,00



Headlight R, Scratch(es), Acceptable

0,00

