



**AUDI A4 AVANT: 1LPD588**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WAUZZZ8K1FA185702</b> | Versionname: | <b>2.0 TDI ULTRA 100KW</b> |
| First Registrationdate:            | <b>3/11/2015</b>         | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>171201</b>            | Power Kw:    | <b>100</b>                 |
| Bodytype:                          |                          | Body color:  | <b>Black</b>               |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2722</b>                |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                                 |
|--------------------------------|---------------------------------|
| Radio CD                       | Central consol F                |
| GPS storage                    | Luggage cover                   |
| GPS storage                    | <b>DVD</b> Rear parking sensors |
| Windows electric F             |                                 |
| Windows electric R             |                                 |
| Cruise Control                 |                                 |
| Steering wheel multifunctional |                                 |
| Seats F heated                 |                                 |
| Radio multimedia               |                                 |
| Type of headlighting           | <b>Headlighting Halogen</b>     |
| Type of GPS                    | <b>GPS big screen color</b>     |
| Type of Lining                 | <b>Lining leather</b>           |
| Type of climate control        | <b>Autom climate control</b>    |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                         |       |                         |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                         |       |                         |
| Winter tyres: | Fr.L.                            | <b>Uniroyal: 4 mm</b>   | Fr.R. | <b>Uniroyal: 4 mm</b>   |
|               | Re.L.                            | <b>Vredestein: 4 mm</b> | Re.R. | <b>Vredestein: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

Total cost ex VAT 809,64

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

|   |        |
|---|--------|
| <i>No pictures to display</i>                           |        |
| Wing R L, Scratch(es), Acceptable                       | 0,00   |
| <i>No pictures to display</i>                           |        |
| Door R L, Scratch(es), Acceptable                       | 0,00   |
| <i>No pictures to display</i>                           |        |
| Door R R, Dent(s), Acceptable                           | 0,00   |
| <i>No pictures to display</i>                           |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



|  |        |
|--|--------|
| Windscreen, Stone chip(s), E - Replace | 487,20 |
|--|--------|



|   |        |
|---|--------|
| Door F L, Scratch(es), Acceptable               | 0,00   |
| <i>No pictures to display</i>                   |        |
| Alloy rim F R, Scratch(es), Acceptable          | 0,00   |
| <i>No pictures to display</i>                   |        |
| Trunk lid covering R, Scratch(es), Smart repair | 110,64 |

