


AUDI A6 AVANT: 1JXJ426

Vinnumber:	WAUZZ4G7FN067020	Versionname:	2.0 TDI ULTRA 140KW
First Registrationdate:	12/03/2015	Fiscalpower:	
Expertise Mileage:	155666	Power Kw:	140
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	908,32
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Dent(s), Acceptable 0,00



Alloy rim R L, Scratch(es), I - Repair 100,00



Alloy rim F L, Scratch(es), I - Repair 100,00



Alloy rim R R, Scratch(es), I - Repair 100,00



Wing R L, Scratch(es), Acceptable 0,00



Interior, Worn, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16





Alloy rim F R, Scratch(es), I - Repair

100,00

