



BMW 3 BERLINE: 1KKK876

Vinnumber:	WBA3E11060F949176	Versionname:	2.0 320D EFFICIENTDYN. (120KW) BERLINE
First Registrationdate:	20/05/2015	Fiscalpower:	
Expertise Mileage:	88900	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4604
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1155,43
--------------------------	----------------

Bodywork, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Tyre repair kit, Missing, E - Replace 210,53



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Compressor, Missing, E - Replace 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display