



BMW 3: 1HAE319			
Vinnumber:	WBA3D11000J853947	Versionname:	3 BER 318dA 136PK Aut.
First Registrationdate:	3/06/2014	Fiscalpower:	
Expertise Mileage:	159681	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1327
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2557,91
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	338,08



Door R R, Dent(s), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper F, Dent(s) and scratch(es), Le - Replace and paint

735,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Outer door handle F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display