



BMW 4 GRAN COUPE: 1LNZ481

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnnumber: | WBA4E71060GS99864 | Versionname: | 2.0 418D (100KW) GRAN COUPE |
| First Registrationdate: | 2/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 133870 | Power Kw: | 100 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 1415 |
| Maintenance: | IN 14000 KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | | Seats electric F R | |
| GPS storage | HD | Sun Roof electric | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Seats F heated | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|----------------------|-------|----------------------|
| 225/45/18/91 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Pirelli: 0 mm | Fr.R. | Pirelli: 0 mm |
| | Re.L. | Pirelli: 0 mm | Re.R. | Pirelli: 0 mm |

Assistance equipment

| | | |
|--|---------|------------|
| | Runflat | Yes |
| Total cost ex VAT | | 332,44 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | 95,00 |



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 125,16



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding R Mid, Scratch(es), E - Replace 17,28

