



BMW X1: 1NAH138

Vinnumber:	WBAHT710905E09134	Versionname:	2.0 SDRIVE18D (100KW)
First Registrationdate:	4/01/2016	Fiscalpower:	
Expertise Mileage:	116119	Power Kw:	100
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4720
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric
Windows electric R	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining artificial leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/50/18/92 MS LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1434,14
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)		95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), E - Replace

0,00



Bumper F M, Dent(s) and scratch(es), LI - Repair and paint (partial)

110,64



Bonnet, Dent(s) and scratch(es), Le - Replace and paint

1016,70

