



BMW X4: 1LGP555			
Vinnumber:	WBAXX110000R36941	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	23/09/2015	Fiscalpower:	
Expertise Mileage:	72174	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/60/17/99 H LightMetal			
	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment			
		Runflat	Yes
Total cost ex VAT			3928,83
Bumper F, Broken, Le - Replace and paint			862,80



Wing moulding F L, Scratch(es), E - Replace 99,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Xenon headlight R, Scratch(es), E - Replace 696,00



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Wing F R, Dent(s), Le - Replace and paint 612,02



Roof, Dent(s), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, Smart repair 64,32



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Headrest R M, Damaged, Smart repair 110,64



Bumper cover R M, Scratch(es), Smart repair 110,64

