



BMW X3: 1HTP591			
Vinnumber:	WBAWZ310100F63798	Versionname:	X3 2.0d sDrive18 136PK
First Registrationdate:	30/09/2014	Fiscalpower:	
Expertise Mileage:	142238	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1713
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/17/103 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1454,23
Wheel arch cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper spoiler F, Missing, E - Replace	84,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Crack, E - Replace 30,00



Wing F L, Repaired, Acceptable 0,00

No pictures to display

Roof, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Bumper R, Dent(s), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

