



RENAULT SCENIC: 1JVZ766

Vinnumber:	VF1JZ500E52762352	Versionname:	1.5 DCI 110 EDC BOSE EDITION
First Registrationdate:	10/03/2015	Fiscalpower:	
Expertise Mileage:	56319	Power Kw:	81
Bodytype:		Body color:	Burgundy
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3313
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
	Rear parking sensors

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1738,66
-------------------	----------------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Wing R L, Bad repair, LI - Repair and paint (complete) 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L polished, Rust, Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Dent(s), E - Replace 415,20



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

