


TOYOTA Auris: 1FWF225

Vinnumber:	SB1Z53JE90E055843	Versionname:	AURIS TOUR.SP. HSD Lounge CVT 99PK Aut.
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	81546	Power Kw:	73
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	2806
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	1371,80
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Deformed / Strained, LI - Repair and paint (complete)	259,80



Rear window, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

259,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Scratch(es), E - Replace

0,00



Door panel R L, Scratch(es), E - Replace

114,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---------------------------------------------------------	--------



Boot cover, Scratch(es), E - Replace	50,00
--------------------------------------	-------

