



**SKODA SUPERB: 1LPR415**

Vinnumber:	<b>TMBAH9NP8G7027052</b>	Versionname:	<b>2.0 CRTDI 110KW DSG6 STYLE</b>
First Registrationdate:	<b>6/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>182035</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3211</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
GPS storage	<b>HD</b>	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/40/19/96 Y LightMetal</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 4 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Vredestein: 5 mm</b>	Re.R.	<b>Vredestein: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>95,00</b>
<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable

0,00

*No pictures to display*