



VOLKSWAGEN Transporter: 1HCE861

| | | | |
|------------------------------------|---------------------------------|--------------|---------------------------------|
| Vinnumber: | WV1ZZZ7HZFH001607 | Versionname: | TRANSP.1200 B/F SWB 84PK |
| First Registrationdate: | 17/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 105606 | Power Kw: | 62 |
| Bodytype: | | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1729 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|----------------------------------|-----------------|-------------------|
| Radio CD | | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|----------------------|-------|----------------------|
| | 205/65/16/105 T Steel | | | |
| Winter tyres: | Fr.L. | Pirelli: 4 mm | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Pirelli: 4 mm | Re.R. | Pirelli: 4 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---------------------------------------|---------------|
| Total cost ex VAT | 199,00 |
| Tailgate, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover F L, Missing, E - Replace | 0,00 |



| | |
|---------------------------------------|------|
| Wheel cover R L, Missing, E - Replace | 0,00 |
|---------------------------------------|------|



| | |
|---|------|
| Bodywork, Not original part, Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---------------------------------------|------|
| Wheel cover R R, Missing, E - Replace | 0,00 |
|---------------------------------------|------|



| | |
|---|-------|
| Trunk lid covering R, Broken, E - Replace | 49,00 |
|---|-------|



| | |
|--|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display