



VOLKSWAGEN GOLF SPORTSVAN: 1LGF446

| | | | |
|------------------------------------|---------------------------------|--------------|---|
| Vinnumber: | WVWZZZAUZGW533279 | Versionname: | 1.6 TDI 81KW DSG-7 TRENDLINE BMT |
| First Registrationdate: | 21/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 161858 | Power Kw: | 81 |
| Bodytype: | | Body color: | White |
| Gearbox: | Automatic | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4433 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 2 | | |
| Number head rests: | 2 | | |
| Rims summer: | Aluminium | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Front parking sensors |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 195/65/15/92 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-------------|-----------|------|------------|
| Spare wheel | No | Jack | Yes |
|-------------|-----------|------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1541,15 |
|-------------------|----------------|

| | |
|---|---------------|
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 0,00



Door F R, Dent(s), LI - Repair and paint (complete) 414,35



Bumper grille, Crack, E - Replace 32,40



Door panel R L, Scratch(es), E - Replace 114,00



Seat cover F R, Stain, E - Replace 360,00



Spare wheel, Missing, E - Replace 196,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Rust, Acceptable 0,00

