



VOLKSWAGEN Caddy: 1JEE678

Vinnumber:	WV2ZZZ2KZFX055127	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	145399	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4721
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Kleber: 3 mm	Re.R.	Kleber: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1223,00
Wing F L, Dent(s) and scratch(es), Le - Replace and paint	427,51



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk lid covering R, Scratch(es), Acceptable 0,00



Seat cover F R, Stain, Acceptable 0,00



Seat cover R L, Damaged, Smart repair 64,32



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00



Wheel cover F R, Broken, E - Replace 22,50



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), LI - Repair and paint (complete) 238,76





Bumper R, Unclashed, N - Mount/Dismount

0,00



Seat cover F L, Stain, Acceptable

0,00

