



**VOLKSWAGEN GOLF: 1TKS772**

Vinnnummer:	<b>WVWZZZ1KZAP167941</b>	Versionname:	
First Registrationdate:	<b>20/05/2010</b>	Fiscalpower:	<b>103</b>
Expertise Mileage:	<b>208177</b>	Power Kw:	<b>Grey</b>
Bodytype:		Body color:	<b>Metalic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Aluminium</b>
Transmission:	<b>Front</b>	Rims summer:	<b>OK</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>2222</b>
Battery functioning:	<b>Yes</b>	Parking lot:	
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Other: 4 mm</b>	Fr.R.	<b>Other: 4 mm</b>
	Re.L.	<b>Other: 4 mm</b>	Re.R.	<b>Other: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>909,80</b>
<b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>



Ignition key, Missing, E - Replace

150,00



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Door R L, Dent(s), Acceptable

0,00

*No pictures to display*

Bonnet, Bad repair, Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Dent(s), Acceptable

0,00

*No pictures to display*

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Engine protective plate, Deformed / Strained, E - Replace

50,00



Certificate Of Conformity, Missing, E - Replace

150,00



Mirror side blinker R, Scratch(es), Acceptable

0,00

*No pictures to display*