



VOLKSWAGEN GOLF VARIANT: 1JLY714

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber: | WVWZZZAUZFP587059 | Versionname: | 1.6 CR TDI 77KW DSG BMT TRENDLINE |
| First Registrationdate: | 20/01/2015 | Fiscalpower: | |
| Expertise Mileage: | 139108 | Power Kw: | 77 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3121 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | Tow bar fixed |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/92 MS Steel | | | |
| Winter tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 211,80 |
|-------------------|--------|

| | |
|-------------------------------|------|
| Door F L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



Rear window, Scratch(es), E - Replace 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display