



MERCEDES CLA: 1KUZ479

Vinnumber:	WDD1173121N254114	Versionname:	1.5 CLA 180 CDI
First Registrationdate:	9/07/2015	Fiscalpower:	
Expertise Mileage:	90762	Power Kw:	80
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4712
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	BF Goodrich: 8 mm	Fr.R.	BF Goodrich: 8 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1087,80
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	235,80



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s), LI - Repair and paint (complete) 235,80



Spoiler R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display

Sill outer R, Chemical polution, Acceptable 0,00



Tailgate, Chemical pollution, Acceptable

0,00

No pictures to display