



VOLKSWAGEN Transporter: 1HBP709

Vinnumber:	WV1ZZZ7HZEH133075	Versionname:	TRANSP.1200 B/F SWB 84PK
First Registrationdate:	12/06/2014	Fiscalpower:	
Expertise Mileage:	158147	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2306
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/92 H Steel			
Summer tyres:	Fr.L. Vredestein: 5 mm	Fr.R. Vredestein: 5 mm	
	Re.L. Vredestein: 6 mm	Re.R. Vredestein: 6 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 757,81

Rearview mirror housing R, Scratch(es), Smart repair 110,64



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Deformed / Strained, E - Replace 329,40



Bumper F, Dent(s), Smart repair 110,64



Rear bulkhead lining, Hole, E - Replace 42,00



Wing F R, Dent(s), LI - Repair and paint (complete) 165,13



Seat cover F L, Damaged, Acceptable 0,00

