



VOLKSWAGEN Transporter: 1GXQ850

| | | | |
|------------------------------------|---------------------------------|--------------|---------------------------------|
| Vinnumber: | WV1ZZZ7HZEH129690 | Versionname: | TRANSP.1200 B/F SWB 84PK |
| First Registrationdate: | 28/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 51892 | Power Kw: | 62 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | LCV18 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|----------------------------------|------------------|-------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|------------------------------|-------|----------------------|-------|----------------------|
| 205/65/16/107 T Steel | | | | |
| Summer tyres: | Fr.L. | Hankook: 7 mm | Fr.R. | Hankook: 7 mm |
| | Re.L. | Hankook: 7 mm | Re.R. | Hankook: 7 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 323,95 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|----------------------------------|--------------|
| Rearlight R , Crack, E - Replace | 91,50 |
|----------------------------------|--------------|



| | |
|---|-------------|
| Bumper F, Chemical polution, Acceptable | 0,00 |
|---|-------------|

No pictures to display

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Fuel cap cover, Deformed / Strained, E - Replace 14,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Bodywork, Not original part, Remove lettering 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display