


OPEL ASTRA SPORTS TOURER: 1LJL286

Vinnumber:	WOLPD8E6XG8008759	Versionname:	1.6 CDTI 81kW ecoFLEX S/S Ultimate Ed.
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	162990	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	Yes	Parking lot:	PARKING VOORAAN
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	HD		
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		














Total cost ex VAT	869,98
--------------------------	---------------

Wheel cover F L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing R L, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Engine, Not functioning (well), Acceptable	0,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)	115,56
 	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
  	
Trunk lid covering R, Scratch(es), Smart repair	110,64
  	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
 	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
 	
Door R L, Dent(s), Acceptable	0,00
No pictures to display	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
No pictures to display	