



## VOLKSWAGEN Transporter: 1FXJ893

Vinnumber:	<b>WV1ZZZ7HZDH038754</b>	Versionname:	<b>TRANSP.1200 B/F SWB 84PK</b>
First Registrationdate:	<b>11/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>154045</b>	Power Kw:	<b>62</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2308</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

<b>205/65/16/105 T Steel</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>00</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	262,00
Seat cover F L, Worn, Acceptable	0,00
No pictures to display	
Ignition key, Missing, E - Replace	150,00
No pictures to display	
Tailgate, Dent(s), Acceptable	0,00
No pictures to display	
Bodywork, Not original part, Acceptable	0,00
No pictures to display	

Trunk lid covering R, Crack, E - Replace

49,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Chemical polution, Acceptable

0,00

*No pictures to display*

Bumper F, Chemical polution, Acceptable

0,00

*No pictures to display*

Sliding door R, Dent(s), PDR - Paintless dent repair

63,00

