



MERCEDES CLA: 1NCV729

Vinnnumber:	WDD1179121N323304	Versionname:	
First Registrationdate:	25/01/2016	Fiscalpower:	
Expertise Mileage:	103304	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3210
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1846,62
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Sill outer L, Scratch(es), It - Spot repair

115,56



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), It - Spot repair

115,56



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

342,35



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Seat cover F L, Stain, Cleaning

25,00



Bumper R, Bad repair, LI - Repair and paint (complete)

0,00




Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rear window, Scratch(es), E - Replace

370,00



Maintenance, Maintenance, Execute

0,00

No pictures to display