



PEUGEOT 308 SW: 1KTF287

Vinnumber:	VF3LCBHY8FS167441	Versionname:	1.6 BLUEHDI 73KW S/S ACTIVE
First Registrationdate:	29/06/2015	Fiscalpower:	
Expertise Mileage:	110465	Power Kw:	73
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	+ 2900 KM	Parking lot:	4124
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	718,91
-------------------	---------------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair

115,56



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Roof, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

