


RENAULT Grand Scenic: 1HES852

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF1JZ14M650883443 | Versionname: | GRAND SCENIC Energy R-Movie 5pl.110PK |
| First Registrationdate: | 2/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 123483 | Power Kw: | 81 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | 3425 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|----------------------------------|-----------------------|--------------------------|
| Radio CD | | Central consol F | |
| TV/DVD screen R | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar removable |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Alarm | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|----------------------|-------|----------------------|
| 205/55/17/92 MS LightMetal | | | | |
| Winter tyres: | Fr.L. | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
| | Re.L. | Pirelli: 6 mm | Re.R. | Pirelli: 6 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

Total cost ex VAT 465,00

Maintenance, Maintenance, Execute 0,00

No pictures to display

Seat cover F L, Damaged, Acceptable 0,00



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|--------|
| Rear window, Scratch(es), E - Replace | 370,00 |
|---------------------------------------|--------|



| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

