



## VOLKSWAGEN PASSAT VARIANT: 1KHF637

Vinnumber:	<b>WVWZZZ3CZFE498824</b>	Versionname:	<b>1.6 TDI VARIANT COMFORTLINE</b>
First Registrationdate:	<b>5/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>170943</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4702</b>
Maintenance:	<b>17400</b>		
Maintenance:	<b>216 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>885,16</b>
Roof pillar L, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Scratch(es), LI - Repair and paint (complete)			<b>211,80</b>



Bumper F, Scratch(es), It - Spot repair

115,56



Door R L, Repaired, Acceptable

0,00

*No pictures to display*

Wing F L, Repaired, Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Internal Boot Lining R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Windscreen, Repaired, Acceptable

0,00

*No pictures to display*

Door frame R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Seat cover R, Stain, Cleaning

25,00



Wing R L, Repaired, Acceptable

0,00

No pictures to display

Door R L, Repaired, Acceptable 0,00

No pictures to display

Roof pillar R, Dent(s), PDR - Paintless dent repair 82,80



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 0,00



Seat cover F R, Stain, Cleaning 25,00



Shutter / cover, Broken, Forfeit 10,00



Door panel F L, Worn, Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Tires, Not original part, Acceptable 0,00

No pictures to display

Glove compartment lid, Scratch(es), Acceptable 0,00

No pictures to display