



VOLVO XC60: 1LNJ714

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber: | YV1DZARCDG2854149 | Versionname: | 2.0 D3 2WD GEARTRONIC MOMENTUM |
| First Registrationdate: | 28/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 63918 | Power Kw: | 110 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1716 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | HD | Panoramic roof | |
| GPS storage | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | Tow bar removable |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | NOT OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 235/65/17/108 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Goodyear: 3 mm | Re.R. | Goodyear: 3 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |



| | |
|--------------------------|---------------|
| Total cost ex VAT | 369,84 |
|--------------------------|---------------|

| | |
|--|-------------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|--|-------------|

| | |
|-------------------------------|--|
| <i>No pictures to display</i> | |
|-------------------------------|--|

| | |
|---|-------------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|---|-------------|

| | |
|-------------------------------|--|
| <i>No pictures to display</i> | |
|-------------------------------|--|

| | |
|---|--------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), E - Replace | 0,00 |
|  | |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Dent(s), LI - Repair and paint (complete) | 369,84 |
|  | |
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |