



RENAULT CLIO: 1LTF992

Vinnumber:	VF15RJL0H53251658	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	30/11/2015	Fiscalpower:	
Expertise Mileage:	45015	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4117
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 MS Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	860,14
-------------------	---------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	24,00
---	--------------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 294,56



Bumper grille, Crack, E - Replace 30,72



Wheel cover R L, Scratch(es), E - Replace 24,00



Tyre repair kit, Missing, E - Replace 168,42



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F R, Scratch(es), E - Replace 24,00



Roof, Hail damage, PDR - Hail 125,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display