


**RENAULT Kangoo Express: 1FJK672**

Vinnumber:	<b>VF1FW58H549448094</b>	Versionname:	<b>KANGOO EXPR.MAXI Energy Gr.Conf.90PK</b>
First Registrationdate:	<b>16/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>142756</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>KT</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/95 T Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	2033,60
-------------------	---------

Sill outer L, Dent(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Sliding door R, Dent(s) and scratch(es), It - Spot repair

115,56



Ignition key, Missing, E - Replace

150,00

*No pictures to display*

Wheel cover F R, Missing, E - Replace

22,50



Wheel cover F L, Scratch(es), E - Replace

22,50



Aerial, Damaged, E - Replace

11,25



Door F L, Dent(s), Acceptable

0,00

*No pictures to display*

Bumper R, Crack, E - Replace

329,40



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper F, Crack, E - Replace

398,40



Wheel cover R L, Scratch(es), E - Replace

22,50



Roof, Rust, LI - Repair and paint (complete)

361,13



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Roof, Not original part, Acceptable 0,00

No pictures to display