



BMW X3: 1JJP871

Vinnumber:	WBAWZ310000K94397	Versionname:	X3 2.0dA sDrive18 136PK Aut.
First Registrationdate:	5/01/2015	Fiscalpower:	
Expertise Mileage:	124336	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3606
Maintenance:	IN 29000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Total cost ex VAT	778,09
-------------------	--------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Interior, Dirty, Chemical cleaning	100,00
------------------------------------	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), PDR - Paintless dent repair 63,00



Spoiler R, Dent(s), E - Replace 150,37



Bumper R, Dent(s), LI - Repair and paint (complete) 254,16



Bumper F L, Scratch(es), It - Spot repair 115,56





Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	