



**VOLKSWAGEN TOURAN: 1NEG017**

Vinnumber:	<b>WVGZZZ1TZGW548574</b>	Versionname:	<b>2.0 TDI SCR 110KW DSG-6 HIGHLINE</b>
First Registrationdate:	<b>3/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>91057</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4719</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>7</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-Alcantara</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>2116,73</b>
Rear window, Scratch(es), E - Replace			<b>0,00</b>



Door R L, Dent(s), Acceptable 0,00

*No pictures to display*

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R polished, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Deformed / Strained, Le - Replace and paint 735,00



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Sill outer R, Scratch(es), It - Spot repair 115,56



Alloy rim R L polished, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F R, Dent(s) and scratch(es), Le - Replace and paint 530,02



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80

