



AUDI A3 SPORTBACK: 1LBN602

Vinnumber:	WAUZZZ8V7GA023858	Versionname:	1.6 TDI 81KW ATTRACTION
First Registrationdate:	11/08/2015	Fiscalpower:	
Expertise Mileage:	78169	Power Kw:	81
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3224
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/92 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	1417,05
Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50



Roof, Hail damage, PDR - Hail

0,00



Tyre F R, Deformed / Strained, E - Replace

132,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), E - Replace

0,00

