



BMW 3 GRAN TURISMO: 1NDZ113

Vinnumber:	WBA8Y510X0G436916	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	1/02/2016	Fiscalpower:	
Expertise Mileage:	98826	Power Kw:	100
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OVERSCHREDEN SINDS 900 KM	Parking lot:	2205
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT 294,12

Door frame R L, Scratch(es), Acceptable 0,00

Door F R, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), It - Spot repair

115,56



Door R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Maintenance, Maintenance, P - Check

0,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Dent(s), Acceptable

0,00

No pictures to display