



**MERCEDES CLA SHOOTING BRAKE: 1KTP322**

Vinnumber:	<b>WDD1179081N230164</b>	Versionname:	<b>2.1 CLA 200 CDI SHOOTING BRAKE</b>
First Registrationdate:	<b>1/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>135309</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICEBEURT A3 OVER 335 DAGEN</b>	Parking lot:	<b>1232</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining semi-artificial leather</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>473,44</b>
Bumper F, Scratch(es), Acceptable	<b>0,00</b>



Windscreen, Stone chip(s), Acceptable

0,00



Door panel F L, Worn, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Backrest cover F L, Worn, Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Interior, Dirty, Cleaning

25,00





Boot cover, Scratch(es), Acceptable

0,00



Internal Boot Lining R, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), Acceptable

0,00



Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00

