


**MERCEDES C BERLINE: 1LTT408**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WDD2050371R129192</b> | Versionname: | <b>1.6 C 200 D AVANTGARDE</b> |
| First Registrationdate:            | <b>2/12/2015</b>         | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>72555</b>             | Power Kw:    | <b>100</b>                    |
| Bodytype:                          | <b>Berline</b>           | Body color:  | <b>Grey</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1125</b>                   |
| Number of doors:                   | <b>4</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                                       |                       |
|--------------------------------|---------------------------------------|-----------------------|
| GPS storage                    | <b>SD</b>                             | Central consol F      |
| GPS storage                    |                                       | Front parking sensors |
| Windows electric F             |                                       | Rear parking sensors  |
| Windows electric R             |                                       |                       |
| Cruise Control                 |                                       |                       |
| Steering wheel multifunctional |                                       |                       |
| Radio multimedia               |                                       |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>           |                       |
| Type of GPS                    | <b>GPS big screen color</b>           |                       |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |                       |
| Type of climate control        | <b>Autom climate control</b>          |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                       |       |                       |
|-----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/50/17/98 MS LightMetal</b> |       |                       |       |                       |
| Summer tyres:                     | Fr.L. | <b>Pirelli: 4 mm</b>  | Fr.R. | <b>Pirelli: 4 mm</b>  |
|                                   | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|  |            |            |              |
|--|------------|------------|--------------|
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>   |
| Total cost ex VAT  |            |            | <b>95,00</b> |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b> |

