



|                         |                    |              |           |
|-------------------------|--------------------|--------------|-----------|
| <b>KOGA : F0020015</b>  |                    |              |           |
| Vinnumber:              | XXXXXXXXXXF0020015 | Versionname: |           |
| First Registrationdate: | 4/08/2014          | Fiscalpower: |           |
| Expertise Mileage:      | 278                | Power Kw:    |           |
| Bodytype:               |                    | Body color:  | Grey      |
| Gearbox:                | MAN 8 VIT          | Paint type:  | Metalic   |
| Transmission:           | Back               | Rims summer: | Aluminium |
| Fueltype:               |                    | Oil level:   | OK        |
| Battery functioning:    | Yes                |              |           |
| Number of doors:        | 1                  |              |           |
| Number of seats:        | 1                  |              |           |
| Number head rests:      | 0                  |              |           |
| Rims summer:            | Aluminium          |              |           |
| Category:               | VS                 |              |           |
| Oil level:              | OK                 |              |           |

|                                |                           |
|--------------------------------|---------------------------|
| <b>Options</b>                 |                           |
| Steering wheel multifunctional |                           |
| Type of headlighting           | Headlighting LED          |
| Type of Lining                 | Lining artificial leather |

|                                     |    |                     |     |
|-------------------------------------|----|---------------------|-----|
| <b>Limited Technical Inspection</b> |    |                     |     |
| Airco functioning                   | OK | Battery functioning | Yes |
| Tires wear profile                  | OK | Power steering      | Yes |
| Idle position                       | OK | Sound engine        | OK  |
| Engine startingtime                 | OK | Clutch test         | OK  |
| Exhaust gass                        | OK | Wiper fluid level   | OK  |
| Handbrake                           | OK | Transmission        | OK  |
|                                     |    | Lighting            | OK  |
|                                     |    | Wiperblades         | OK  |

|                                   |       |             |       |             |
|-----------------------------------|-------|-------------|-------|-------------|
| <b>Degree of wear</b>             |       |             |       |             |
| <b>28/0/700/35 22B LightMetal</b> |       |             |       |             |
| Summer tyres:                     | Fr.L. | Other: 1 mm | Fr.R. | Other: 1 mm |
|                                   | Re.L. | Other: 1 mm | Re.R. | Other: 1 mm |

|                               |      |
|-------------------------------|------|
| <b>Assistance equipment</b>   |      |
| Total cost ex VAT             | 0,00 |
| Bodywork, Damaged, Acceptable | 0,00 |

