



**VOLKSWAGEN GOLF: 1FIM387**

Vinnnummer:	<b>WVWZZZAUZDW154252</b>	Versionname:	
First Registrationdate:	<b>8/07/2013</b>	Fiscalpower:	<b>77</b>
Expertise Mileage:	<b>123015</b>	Power Kw:	
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4602</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>SD</b>	
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/92 H Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1851,89</b>
-------------------	----------------

Door F L, Dent(s), LI - Repair and paint (complete)	<b>318,35</b>
-----------------------------------------------------	---------------



Windscreen, Scratch(es), 67 - Polish

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

235,80



Wheel cover F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace

370,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R L, Bad repair, LI - Repair and paint (complete)

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

380,20



Bonnet, Stone chip(s), Acceptable

0,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18

