



OPEL COMBO: 1RDV615

Vinnumber:	W0L6ZZU1AH9606350	Versionname:	1.3 CDTi 70KW 2.0T L1H1
First Registrationdate:	25/11/2016	Fiscalpower:	
Expertise Mileage:	55888	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4731
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 H Steel			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	63,00
-------------------	--------------

Trunk door R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------

No pictures to display

no pictures to display